



facsimile transmittal

To: ANDY Fax: 303-861-5466
From: BRANDON Date: 2-14-11
Re: Pages: 5
Cc: From:

Urgent For review Please comment Please reply Please recycle

Notes:

ANDY,
Here are two estimates, one for full repair with parts prices and one with you buying the parts.
We have an appointment with ABBRA at 8:30am today. I will fax that estimate when I have it.

Thanks.

Maaco Collision Repair, Auto Painting & Glass
8085 Blakeland Dr.
Littleton, CO 80125
303-791-1255 phn
303-791-7038 fax

MAACO COLLISION REPAIR & AUTO PAINTING
 8085 BLAKELAND DR
 LITTLETON CO 80125
 303-791-1255 PHONE 303-791-7038 FAX M1008@MAACO.COM EMAIL

***** PRELIMINARY ESTIMATE *****

02/14/2011 07:23 AM

Owner

Owner: DENVER LINCOLN LIMO

Inspection

Inspection Date: 02/14/2011 07:24 AM
Primary Impact: Right Side

Inspection Type:
Secondary Impact:

Appraiser Name: Brandon J Burch
Address: 8085 Blakeland Dr
City State Zip: Littleton, CO 80125
Email: maacolittleton@live.com

Appraiser License # :
Work/Day: (303)791-1255
FAX: (303)791-7038

Repairer

Repairer: 1 Maaco Collision Repair
Address: 8085 Blakeland Dr
City State Zip: Littleton, CO 80125

Contact:
Work/Day: (303)791-1255
FAX: (303)791-7038

Vehicle

2007 Lincoln Town Car Executive L 4 DR Sedan
 8cyl Gasoline 4.6
 4 Speed Automatic

Lic.Plate: IWAIT12
Lic Expire:
Prod Date:
Veh Insp# :
Condition:
Ext. Color: BLK
Ext. Refinish: Two-Stage

Lic State: CO
VIN: 1LNHM84W47Y636819
Mileage: 127,461
Mileage Type: Actual
Code: Q5204A
Int. Color:
Int. Refinish:

Options

Alarm System	Aluminum/Alloy Wheels	Anti-lock Brakes
Auto Load Leveling	Automatic Dimming Mirror	Bodyside Cladding
Cargo/Trunk Net	Compact Disc W/Tape	Cruise Control
Dual Air Conditioning	Dual Airbags	Dual Power Seats
Dual Zone Auto A/C	Floor Mats	Garage Door Opener
Head Airbags	Heated Frnt & Rear Seats	Heated Power Mirrors
Heavy Duty Suspension	Intermittent Wipers	Keyless Entry Keypad
Keyless Entry System	Leather Seats	Leather Steering Wheel
Lighted Entry System	Overhead Console	Power Adjustable Pedals
Power Brakes	Power Door Locks	Power Steering
Power Windows	Rear Seat Audio Controls	Rear Window Defroster
Rem Trunk-L/Gate Release	Side Airbags	Split Front Bench Seat
Strg Wheel Radio Control	Theft Deterrent System	Tilt Steering Wheel
Tinted Glass	Traction Control System	Trip Computer
Wood Interior Trim		

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
------	----	-------	----	-------------	--------------	-------	------	----	-------	---

02/14/2011 07:45 AM

1	E	290	Pnl,Rear Door Outer RT >> CUST PART	3W1Z5424700AA	\$0.00*	7.6	SM
2	L	290	13 Pnl,Rear Door Outer RT	Refinish		4.0	RF
3	RI	368	W/Strip,Rear Door RT	R & I Assembly		INC	SM
4	RI	334	Mldg,Rear Door Scalp R/R	R & I Assembly		INC	SM
5	E	324	Mldg,Rear Door Side RT >> CUST PART	6W1Z5425556APTM	\$0.00*	0.4	SM
6	L	324	Mldg,Rear Door Side RT	Refinish		1.0	RF
7	RI	324	Mldg,Rear Door Side RT	R & I Assembly		INC	SM
8	RI	34	Applique Assy,Rear Dr RT	R & I Assembly		0.5	SM
9	RI	308	Pnl,Inner Door Trim RT	R & I Assembly		INC	SM
10	RI	1293	Switch,Rear Door RT	R & I Assembly			SM
11	RI	306	Handle,RR Door Outer RT	R & I Assembly		INC	SM
12	L	M14	Corrosion Protection	Refinish		0.3*	RF
13	EC	M60	Hazardous Waste Removal	Replace Economy	\$5.00*		SM
14	EC		BODY REPAIR MATERIALS	Replace Economy	\$69.95*		SM*
15	EC		SOUND PAD	Replace Economy	\$65.00*		SM*
15 Items							

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Other Parts	\$139.95	
Paint Materials	\$159.00	
Parts & Material Total		\$298.95
Tax on Parts & Material	@ 5.100%	\$15.25

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$48.00	8.5		8.5	\$408.00
Mech/Elec (ME)	\$99.00				
Frame (FR)	\$80.00				
Refinish (RF)	\$48.00	5.3		5.3	\$254.40
Paint Materials	\$30.00				

Labor Total	13.8 Hours	\$662.40
Gross Total		\$976.60
Net Total		\$976.60



Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 80125 Default

Audatex Estimating 6.0.514 ES 02/14/2011 07:45 AM REL 6.0.514 DT 01/01/2011
 Copyright (C) 2010 Audatex North America, Inc.

1.3 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES, IF ANY, APPLICABLE TO THESE REPLACEMENT CRASH PARTS ARE PROVIDED BY THE PARTS MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

IT IS UNLAWFUL TO KNOWINGLY PROVIDE FALSE, INCOMPLETE, OR MISLEADING FACTS OR INFORMATION TO AN INSURANCE COMPANY FOR THE PURPOSE OF DEFRAUDING OR ATTEMPTING TO DEFRAUD THE COMPANY. PENALTIES MAY INCLUDE IMPRISONMENT, FINES,

MAACO COLLISION REPAIR & AUTO PAINTING
 8085 BLAKELAND DR
 LITTLETON CO 80125
 303-791-1255 PHONE 303-791-7038 FAX M1008@MAACO.COM EMAIL

*** PRELIMINARY ESTIMATE ***

02/14/2011 07:23 AM

Owner

Owner: DENVER LINCOLN LIMO

Inspection

Inspection Date: 02/14/2011 07:24 AM
 Primary Impact: Right Side

Inspection Type:
 Secondary Impact:

Appraiser Name: Brandon J Burch
 Address: 8085 Blakeland Dr
 City State Zip: Littleton, CO 80125
 Email: maacolittleton@live.com

Appraiser License # :
 Work/Day: (303)791-1255
 FAX: (303)791-7038

Repairer

Repairer: 1 Maaco Collision Repair
 Address: 8085 Blakeland Dr
 City State Zip: Littleton, CO 80125

Contact:
 Work/Day: (303)791-1255
 FAX: (303)791-7038

Vehicle

2007 Lincoln Town Car Executive L 4 DR Sedan
 8cyl Gasoline 4.6
 4 Speed Automatic

Lic.Plate: IWAIT12
 Lic Expire:
 Prod Date:
 Veh Insp# :
 Condition:
 Ext. Color: BLK
 Ext. Refinish: Two-Stage

Lic State: CO
 VIN: 1LNHM84W47Y636819
 Mileage: 127,461
 Mileage Type: Actual
 Code: Q5204A
 Int. Color:
 Int. Refinish:

Options

Alarm System	Aluminum/Alloy Wheels	Anti-lock Brakes
Auto Load Leveling	Automatic Dimming Mirror	Bodyside Cladding
Cargo/Trunk Net	Compact Disc W/Tape	Cruise Control
Dual Air Conditioning	Dual Airbags	Dual Power Seats
Dual Zone Auto A/C	Floor Mats	Garage Door Opener
Head Airbags	Heated Frnt & Rear Seats	Heated Power Mirrors
Heavy Duty Suspension	Intermittent Wipers	Keyless Entry Keypad
Keyless Entry System	Leather Seats	Leather Steering Wheel
Lighted Entry System	Overhead Console	Power Adjustable Pedals
Power Brakes	Power Door Locks	Power Steering
Power Windows	Rear Seat Audio Controls	Rear Window Defroster
Rem Trunk-L/Gate Release	Side Airbags	Split Front Bench Seat
Strg Wheel Radio Control	Theft Deterrent System	Tilt Steering Wheel
Tinted Glass	Traction Control System	Trip Computer
Wood Interior Trim		

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
------	----	-------	----	-------------	--------------	-------	------	----	-------	---

1	E	290		Pnl,Rear Door Outer RT	3W1Z5424700AA	\$1,305.28	7.6	SM
2	L	290	13	Pnl,Rear Door Outer RT	Refinish		4.0	RF
3	RI	368		W/Strip,Rear Door RT	R & I Assembly		INC	SM
4	RI	334		Mldg,Rear Door Scalp R/R	R & I Assembly		INC	SM
5	E	324		Mldg,Rear Door Side RT	6W1Z5425556APTM	\$376.40	0.4	SM
6	L	324		Mldg,Rear Door Side RT	Refinish		1.0	RF
7	RI	324		Mldg,Rear Door Side RT	R & I Assembly		INC	SM
8	RI	34		Applique Assy,Rear Dr RT	R & I Assembly		0.5	SM
9	RI	308		Pnl,Inner Door Trim RT	R & I Assembly		INC	SM
10	RI	1293		Switch,Rear Door RT	R & I Assembly			SM
11	RI	306		Handle,RR Door Outer RT	R & I Assembly		INC	SM
12	L	M14		Corrosion Protection	Refinish		0.3*	RF
13	EC	M60		Hazardous Waste Removal	Replace Economy	\$5.00*		SM
14	EC			BODY REPAIR MATERIALS	Replace Economy	\$69.95*		SM*
15	EC			SOUND PAD	Replace Economy	\$65.00*		SM*
15 Items								

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts		\$1,681.68			
Other Parts		\$139.95			
Paint Materials		\$159.00			
Parts & Material Total			\$1,980.63		
Tax on Parts & Material	@ 5.100%		\$101.01		
Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$48.00	8.5		8.5	\$408.00
Mech/Elec (ME)	\$99.00				
Frame (FR)	\$80.00				
Refinish (RF)	\$48.00	5.3		5.3	\$254.40
Paint Materials	\$30.00				
Labor Total				13.8 Hours	\$662.40
Gross Total					\$2,744.04
Net Total					\$2,744.04

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 80125 Default

Audatex Estimating 6.0.514 ES 02/14/2011 07:43 AM REL 6.0.514 DT 01/01/2011
Copyright (C) 2010 Audatex North America, Inc.

1.3 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES, IF ANY, APPLICABLE TO THESE REPLACEMENT CRASH PARTS ARE PROVIDED BY THE PARTS MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

IT IS UNLAWFUL TO KNOWINGLY PROVIDE FALSE, INCOMPLETE, OR MISLEADING FACTS OR INFORMATION TO AN INSURANCE COMPANY FOR THE PURPOSE OF DEFRAUDING OR ATTEMPTING TO DEFRAUD THE COMPANY. PENALTIES MAY INCLUDE IMPRISONMENT, FINES, DENIAL OF INSURANCE AND CIVIL DAMAGES. ANY INSURANCE COMPANY OR AGENT OF AN